

★ホーローホミ(○はQGS)

	2	2.5	2.6	3	4	5	6	8	10	12	16
2	●	●	●								
2.5	●	●	●								
3	●	●	●	○	●						
4	●	●	●	○	○	●					
5	●	●	●	○	○	○	●				
6	●	●	●	○	○	○	○	●			
8	●	●	●	○	○	○	○	○	●		
10	●	●	●	○	○	○	○	○	○	●	
12				○	○	○	○	○	○	○	
14								○			
15				○	○	○	○	○	○	○	●
16				○	○	○	○	○	○	○	●
18				●	●	○	○	○			
20				○	○	○	○	○	○	○	●
22				●	●	●	●	●			
25				●	○	○	○	○	○	○	●
30				●	○	○	○	○	○	○	●
35					●	●	○	○	○	○	●
40					●	●	○	○	○	○	●
45					●	●	○	○	○	○	●
50					●	●	○	○	○	○	●

★ホーロー平先

	3	4	5	6	8	10
3	●					
4	●	●				
5	●	●	●			
6	●	●	●	●		
8	●	●	●	●	●	
10	●	●	●	●	●	●
12		●	●	●	●	●
15			●	●	●	●
16			●	●	●	●
20			●	●	●	●
25			●	●	●	●
30			●	●	●	●

★ホーロートガリ

	3	4	5
3	●		
4	●	●	
5	●	●	●
6	●	●	●
8	●	●	●
10	●	●	●

★フランジソケット

	4	5	6	8
6	●			
8	●	●	●	
10	●	●	●	
12	●	●	●	●
15	●	●	●	●
16	●	●	●	●
20	●	●	●	●
25		●	●	●
30				●
35				●
40				●
45				●
50				●

★エビネイルプラグ

SNP-425	●
SNP-535	●
SNP-550	●
SNP-635	●
SNP-650	●

★オールブラブSPS

4 x 25	●
5 x 25	●
5 x 35	●
5 x 50	●
6 x 35	●
6 x 50	●

★四角プラグ

1/8	●
1/4	●
3/8	●
1/2	●

★浮プラグ

1/8	●
1/4	●
3/8	●
1/2	●

★沈プラグ

1/8	●
1/4	●
3/8	●
1/2	●

★冷間螺ホルト Rタイプ

	3	4	5	6	8	10
8	●	●	●			
10	●	●	●	●	●	
12	●	●	●	●	●	
15	●	●	●	●	●	●
20		●	●	●	●	●
25		●	●	●	●	●
30		●	●	●	●	●
35			●	●	●	●
40				●	●	●
45				●	●	●
50				●	●	●

★螺ホルト DIN

	4	5	6	8	10	12
8	●					
10	●	●	●	●		
12	●	●	●			
15	●	●	●	●	●	
20	●	●	●	●	●	●
25	●	●	●	●	●	●
30	●	●	●	●	●	●
35	●	●	●	●	●	●
40	●	●	●	●	●	●
45			●			
50		●	●			

★プレス螺ホルト

	4	5	6
8	●	●	
10	●	●	●
12	●	●	●
15	●	●	●
20	●	●	●
25			●